

AFSC 3E3X1
STRUCTURAL APPRENTICE
CAREER FIELD EDUCATION AND TRAINING PLAN

This change is to be implemented immediately in the field. Compliance with AFI 33-360V1, para 3.54, and other training policies and documentation is required. CFETP 3E3X1, 1 August 2002, is changed as follows:

1. Write-in Changes:

PART I SECTION D – RESOURCE CONSTRAINTS

<u>Page</u>	<u>Para</u>	<u>Action</u>
30	12.1	Delete “Equipment”
30	12.1.1	Add “Equipment” before Constraints. Delete “STS item(s) 39.2.2.1.1., 39.2.2.1.2., 39.2.2.1.5., 39.2.2.1.6., TEMPER Tent (3 ea)” Add : None
30	13.1.1	Delete “Training will remain constrained until additional resources identified in paragraph 12.1.1 are received.” Add “None”
30	13.1.2	Delete “Resource constraints are identified in Paragraph 12.1.1. The constrained course will be implemented until required resources are received.” Add “None”
30	13.1.3	Delete “Complete revision of the 3-level course to meet all training requirements and proficiency codes identified in this CFETP. Add “None”

PART II ATTACHMENT 2 - CAREER PROGRESSION AND INFORMATION

<u>Page</u>	<u>Para</u>	<u>Action</u>
58	39.1.1.4.1 (Roof Repairs)	Change from a Core Task (*) to Diamond Task (◆)
58	39.1.1.4.2 (Exterior Walls)	Change from a Core Task (*) to Diamond Task (◆)
59	39.2.1.1 (Tent Hardbacking: Layout & Install Floor)	Change from a Core Task (*) to Diamond Task (◆)
59	39.2.1.2 (Tent Hardbacking: Layout & Erect Walls)	Change from a Core Task (*) to Diamond Task (◆)

<u>Page</u>	<u>Para</u>	<u>Actions</u>
59	39.2.1.3 (Tent Hardbacking: Layout & Install Rafters)	Change from a Core Task (*) to Diamond Task (◆)
59	39.2.2.1.1 (TEMPER Tent: Assemble)	Delete “/b”
59	39.2.2.1.2 (TEMPER Tent: Erect)	Delete “/b”
59	39.2.2.1.5 (TEMPER Tent: Disassembly)	Delete “/b”
59	39.2.2.1.6 (TEMPER Tent: Storage)	Delete “/b”

PART II ATTACHMENT 4

<u>Page</u>	<u>Para</u>	<u>Actions</u>
74	39.1.1.4.1 (Roof Repairs)	Add: CerTest 8404; change (*) to (◆)
74	39.1.1.4.2 (Exterior Walls)	Add: CerTest 8405; change (*) to (◆)
74	39.1.8.2.1 (Conduct Striping Procedures) Runways)	Add: CerTest 8401, CerTest 8402, CerTest 8403; change (*) to (◆)
74	39.2.1.1 (Tent Hardbacking: Layout & Install Floor)	Add: CerTest 8400; change (*) to (◆)
74	39.2.1.2 (Tent Hardbacking: Layout & Erect Walls)	Add: CerTest 8400; change (*) to (◆)
74	39.2.1.3 (Tent Hardbacking: Layout & Install Rafters)	Add: CerTest 8400; change (*) to (◆)

BY ORDER OF THE SECRETARY OF THE AIR FORCE
MICHAEL E. ZETTLER, Lt Gen, USAF
DCS/Installations and Logistics