

**BY ORDER OF THE INSTALLATION
COMMANDER**



**AIR FORCE INSTRUCTION 11-2C-17,
VOLUME 2**

**CHARLESTON AIR FORCE BASE
Supplement 1**

1 SEPTEMBER 2002

Flying Operations

LOCAL PROCEDURES

COMPLIANCE WITH THIS PUBLICATION IS MANDATORY

NOTICE: This publication is available digitally on the AFDPO WWW site at:
<http://www.e-publishing.af.mil>

OPR: 437 OG/OGV (Lt Col Stephen Dellies)
Supersedes AFI 11-2C-17, Volume 2, CAFBS1,
1 Aug 2000

Certified by: 437 OG/CC (Col William Bender)
Pages: 2
Distribution: F

AFI 11-2C-17 Volume 2, 1 July 2000 is supplemented as follow: This supplement implements local procedures as directed by Air Force Instruction (AFI) 11-2C-17, Volume 2, Chapter 4. These procedures apply to all aircrew members assigned or attached to units of the 437th Airlift Wing (AW) and 315 AW (AFRC). Wing offices referenced in this document refer to those of the 437 AW.

SUMMARY OF REVISIONS

This document is substantially revised and must be completely reviewed.

4.1. General. Emergency Procedure Evaluations (EPE) Program Requirements. All C-17A evaluations will include an Emergency Procedure Evaluations (EPE). Refer to the following website for specific EPE guidance: \\437og-server\public\Intranet\OGV\C-17eval_guide.doc.

4.2. (Added) Selected Emergency Procedures. The following procedures, while not Boldface, require immediate action by the aircrew to ensure safety of the crew/aircraft. The initial steps of the emergency procedures listed below should be able to be accomplished without reference to the aircrew checklist. However, inability to accomplish these steps without reference to the checklist will not in and of itself constitute failure of an evaluation.

4.2.1. (Added) APU Fire. Pilots and loadmasters are expected to accomplish the first two steps of the APU Fire checklist:

4.2.1.1. (Added) ARM Switch - ARM

4.2.1.2. (Added) AGENT - Discharge

4.2.2. (Added) APU Abnormal Start Procedure. Pilots and loadmasters are expected to accomplish the first step of the APU Abnormal Start Procedure:

4.2.2.1. (Added) Return the APU PWR START CONTR Switch to OFF.

4.2.3. (Added) Pitch Runaway Recovery. Pilots are expected to accomplish the first three steps of the Pitch Runaway Recovery:

4.2.3.1. (Added) Airspeed - 280 KCAS to V_{mma}

4.2.3.2. (Added) Aircraft Control - Maintain

4.2.3.3. (Added) STAB TRIM Handles - Split

BROOKS L. BASH, Colonel, USAF
Commander, 437th Airlift Wing